



Victoria Carter-Hall
Manager - Federal Regulatory

AT&T Services, Inc.
1120 20th St., NW, Suite 1000
Washington, DC 20036
T: 202.457.2164
F: 202.457.3072

May 27, 2015

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street, SW
Washington, DC 20554

**Re: Certification of Public Notice of Network Change under Rule 51.329(a);
CC Docket No. 96-98**

Dear Ms. Dortch:

Pursuant to the notification requirements in §51.325 -- §51.335 of the Commission's rules, AT&T hereby submits this Certification of Public Notice of Network Change. A description of the network change is provided below.

<u>Number</u>	<u>Type of Change Planned</u>	<u>Location of Change</u>
ATT20150527L.2	AT&T Southwest will be decommissioning the STPs in the AT&T Wichita Falls, TX area. Carriers who connect with AT&T in the Wichita Falls LATA (548) need to migrate their SS7 linksets. The FSPOI codes will remain the same and are (WCFLTXNIK02/WCFLTXCFK01) . AT&T will transport the SS7 links from the FSPOI to the new STP location in LATA 552. Wichita Falls- LATA-548 WCFLTXCF04W / WCFLTXNI05W Point Code - 249-053-000 / 249-052-000---Alias-249-084-000 Dallas/Fort Worth-LATA-552 DLLSTXTA38W / FTWOTXED36W Point Code - 249-030-000 / 249-031-000--Alias 249-096-000	Wichita Falls, TX

This notice is also available at: <https://ebiznet.att.com/networkreg/>

If you have any questions, please do not hesitate to contact me at (202) 457-2164.

Sincerely,

Attachments

CC: Carmell Weathers

CERTIFICATION OF PUBLIC NOTICE(s) OF NETWORK CHANGE(s) UNDER RULE 51.329(a)

On **May 27, 2015** the following Public Notice(s) of Network Change(s) have been made by
AT&T Southwest Pursuant to Code of Federal Regulations 47, Subsections 51.325 – 51.335.



Richard R. Hatch
Area Manager - Network Regulatory
Telephone: (479) 253-7675 Date: 05/27/2015

The Public Notice(s) can also be obtained on the Internet at:

<https://ebiznet.att.com/networkreg/>

Title(s) of Network Notification(s):

ATT20150527L.2

PUBLIC NOTICE of NETWORK CHANGE UNDER RULE 51.329(a)

Network Disclosure Number: **ATT20150527L.2**

Issue Date: **05/27/2015**

Modification Date: **1st Qtr 2016**

Carrier's Name: **AT&T Southwest**

Carrier's Address: **135 Huntsville Rd, Eureka Springs, AR 72632**

Contact: Your Account Manager or Service Representative

Technical Issues

Richard Hatch
135 Huntsville Rd
Eureka Springs, AR 72632
479 253-7675
rh4979@att.com

Public can be obtained on the Internet at:

Notice: <https://ebiznet.att.com/networkreg/>

Network Change:

AT&T Southwest has developed a project with the plan to eliminate the Nortel DMS STPs in Wichita Falls, Texas. This will require re-homing all the SS7 linksets from the Wichita Falls Nortel DMS STPs (**WCFLTXNIK02/WCFLTXCFK01**) into the Dallas/FortWorth, Texas (**DLLSTXTA38W/FTWOTXED36W**) Tekelec STPs. This change will consolidate STPs in LATA (548) to LATA (552).

Description of Type of Changes Planned:

AT&T Southwest will be decommissioning the STPs in the AT&T Wichita Falls, TX area. Carriers who connect with AT&T in the Wichita Falls LATA (548) need to migrate their SS7 linksets. The FSPOI codes will remain the same and are (**WCFLTXNIK02/WCFLTXCFK01**). AT&T will transport the SS7 links from the FSPOI to the new STP location in LATA 552.

Wichita Falls- LATA-548

WCFLTXCF04W / WCFLTXNI05W
Point Code - 249-053-000 / 249-052-000---Alias-249-084-000

Dallas/Fort Worth-LATA-552

DLLSTXTA38W / FTWOTXED36W
Point Code - 249-030-000 / 249-031-000--Alias 249-096-000

Description of Reasonably Foreseeable Impact of the Planned Changes:

Carriers will need to move their SS7 links and must coordinate the activity with AT&T. AT&T will communicate more details with affected Carriers in 1st Quarter 2016. It is anticipated that Carriers will have to issue ASRs to connect to the FSPOI in the existing LATA (562) and that **Carriers will not have to transport their SS7 links any further than they presently do.** ASRs will need to be issued prior to the cutovers with the existing FSPOI, and the new Far End CLLI and Point Code. The Carriers will need a technician in their Central Office or STP during the maintenance window on the night of the cutover to make changes in the SS7 routing tables with the new set of point codes shown above.

Location of Change:

CLLI Code/Statewide	City	State	Implementation Date
From WCFLTXCF04W / WCFLTXNI05W	Wichita Falls	TX	1st Qtr 2016
To DLLSTXTA38W / FTWOTXED36W	Dallas/Ft. Worth	TX	1st Qtr 2016

Your submission has been accepted

ECFS Filing Receipt -
Confirmation number:
2015527644593**Proceeding**

Name	Subject
INBOX-51.329	Section 251 Network Change Notification

Contact Info

Name of Filer: AT&T
Email Address: vc3624@att.com
Attorney/Author Name: Victoria Carter-Hall

Address

Address For: Filer
Address Line 1: 1120 20th Street NW
Address Line 2: Suite 1000
City: Washington
State: DISTRICT OF COLUMBIA
Zip: 20036

Details

Type of Filing: OTHER

Document(s)

File Name	Custom Description	Size
ATT20150527L.1.pdf	Long-Term Network Disclosure	196 KB
ATT20150527L.2.pdf	Long-Term Network Disclosure	367 KB

Disclaimer

This confirmation verifies that ECFS has received and accepted your filing. However, your filing will be rejected by ECFS if it contains macros, passwords, redlining, read-only formatting, a virus, or automated links to other documents.

Filings are generally processed and made available for online viewing within one business day of receipt. You may use the link below to check on the status of your filing:

<http://apps.fcc.gov/ecfs/comment/confirm?confirmation=2015527644593>

For any problems please contact the Help Desk at 202-418-0193.